

MY05223

Alambumi Palm Oil Mill Sdn. Bhd. Audit Summary Report

Organization:	Alambumi Palm Oil Mill Sdn. Bh	d.			
Address:	Alambumi Palm Oil Mill Sdn. Bhd. (HQ)				
	Lot 2370-2371, 1st Floor, Boulevard Commercial Centre, Jalan Pujut-Lutong, 98000 Miri, Sarawak.				
	Contact Person: Mr Teng Keon (Group Admin and Account Manager)				
	Tel: 085-429319				
	Fax: 085-438319/ 428319				
	Alambumi Palm Oil Mill Sdn. Bh		Miri Dintulu 000	00 Miri Sarawak	
	Lot 79, Sawai Land District, KM 1	ız, Jaiaii i	viiii-birituiu, 960	00 Mill, Salawak	
Standard(s):	MS2530-4 : Part 4 : General prin	ciples	Accreditation	Body(DSM): T STANDARDS	
	for Palm Oil Mills		DEPARTMEN' MALAYSIA		
Representative:	Mr. George Anak Akam (Senior	Mill Mana	iger)		
	Mr. Lau Sie Nguong (Operation	Manager,	HQ)		
Site(s) audited:	Alambumi Palm Oil Mill	Date(s)	of audit(s):	30 th January 2019	
Visit Type:	MSPO Audit Stage 2	Type of Assessi	Certification ment	Main Audit	
Lead auditor:	Dickens Mambu (DM) (LA)	Additional team member(s):		Abdul Khalik (AK) (AM	
		Audit M	ember (AM)		
This report is confide	eport is confidential and distribution is limited to the audit team, client representative and the SGS office.				

1. Audit objectives

The objectives of this audit were:

- to confirm that the management system conforms with all the requirements of the audit standard;
- to confirm that the organization has effectively implemented the planned management system;
- to confirm that the management system is capable of achieving the organization's policy objectives.

2. Scope of certification

The audit covered one site performing certification scope:

Processing of Fresh Fruit Bunches (FFB) and Production of Crude Palm Oil (CPO) and Palm Kernel (PK) in compliance to the MSPO Certification Standard MS2530-4:2013 Part 4: General Principles For Palm Oil Mills

Validation of processes for production and service provision

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main Assessment	Visit n°:	2
CONFIDE	ENTIAL	Document:	GP 7003A	Issue n°:	10	Page n°:	1 of 22



Has this scope been amended as a result of this audit?	☐ Yes	☑ No						
This is a multi-site audit and an Appendix listing all relevant sites and/or remote locations has been established (attached) and agreed with the client	☐ Yes	☑ No						
3. Current audit findings and conclusions								
by the standard(s). The audit methods used were interviews, observation of activities documentation and records.	The audit team conducted a process-based audit focusing on significant aspects/risks/objectives required by the standard(s). The audit methods used were interviews, observation of activities and review of documentation and records. The structure of the audit was in accordance with the audit plan as annexes to this summary report.							
The audit team concludes that the organization \boxtimes has \square has not established an management system in line with the requirements of the standard and demonstrated system to systematically achieve agreed requirements for products or services within organization's policy and objectives.	the ability of t	the						
Number of nonconformities identified: 3 Major 0 Minor								
Therefore the audit team recommends that, based on the results of this audit and the demonstrated state of development and maturity, management system certification be	•							
☐ Granted / ☐ Continued / ☐ Withheld / ☐ Suspended until satisfactory corrective	e action is co	mpleted.						
4. Previous Audit Results								
The results of the last audit of this system have been reviewed, in particular to assure and corrective action has been implemented to address any nonconformity identified. concluded that:								
Any nonconformity identified during previous audits has been corrected and the continues to be effective.	corrective act	ion						
The management system has not adequately addressed nonconformity identified activities and the specific issue has been re-defined in the nonconformity section	• .							
5. Audit Findings								
The audit team conducted a process-based audit focusing on significant aspects/risks methods used were interviews, observation of activities and review of documentation	-	he audit						
The management system documentation demonstrated conformity with the requirement of the audit standard and provided sufficient structure to support implementation and maintenance of the management system.	ents 🛚 Ye	s 🗌 No						
maintenance of the management system.								
The organization has demonstrated effective implementation and maintenance / improvement of its management system.	⊠ Ye	s 🗌 No						

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main	Visit n°:	2
					Assessment		
CONFID	ENTIAL	Document:	GP 7003A	Issue n°:	10	Page n°:	2 of 22



The internal audit program has been fully implemented and demonstrates effectives as a tool for maintaining and improving the management system.	eness/	⊠ Yes	☐ No
The management review process demonstrated capability to ensure the continui suitability, adequacy and effectiveness of the management system.	ng	⊠ Yes	□ No
Throughout the audit process, the management system demonstrated overall conformance with the requirements of the audit standard.		⊠ Yes	□ No
Certification claims are accurate and in accordance with SGS guidance	⊠N/A	☐ Yes	☐ No

6. Significant Audit Trails Followed

The specific processes, activities and functions reviewed are detailed in the Audit Plan. In performing the audit, various audit trails and linkages were developed, including the following primary audit trails, followed throughout:

Organization:	Alambumi Palm Oil Mill Sdn. Bhd.				
Address:	Alambumi Palm Oil Mill Sdn. Bhd.	Alambumi Palm Oil Mill Sdn. Bhd. (HQ)			
	Lot 2370-2371, 1st Floor, Boulevard (Comr	nercial Centre, Ja	ılan P	ujut-Lutong, 98000
	Miri, Sarawak.				
	Contact Person: Mr Teng Keon (Ground	up Ac	dmin and Account	Man	ager)
	Гel: 085-429319				
	Fax: 085-438319/ 428319				
	Alambumi Palm Oil Mill Sdn. Bhd.				
	Lot 79, Sawai Land District, KM 112,	Jala	n Miri-Bintulu, 980	000 M	iri, Sarawak
MPOB License	509026404000		Expiry date:	1.08	3.2018 – 31.07.2019
No.:					
Scope of Activity:	1. Menjual dan mengalih (FFB, PK, 0	CPO,	SPO)		
	2. Membeli dan mengalih (FFB, PK,	CPO,)		
	3. Menyimpan (PK, CPO, SPO)				
Date of certificate i	4. Mengilang (FFB)	Nil (New application)			
Date of Certificate i	Source and validity				
Other Sustainabilit	y Certification N	Nil			
Proposed date of n	ext surveillance audit	oven	nber 2019		
Visit Number:	02 (Stage 2) A	ctual	Visit Date:		30 th January 2019
Visit Due by Date:	Nil Fe	or au	ditor informatio	n only	y
Lead Auditor:	Dickens Mambu (DM)				
Team Member(s):	Abdul Khalik Arbi (AKA)				
Additional	Nil				
Attendees and					
Roles					
Standard(s):	MS2530-4 : Part 4 : General principles	for P	alm Oil Mills		

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main	Visit n°:	2
					Assessment		
CONFIL	ENTIAL	Document:	GP 7003A	Issue n°:	10	Page n°:	3 of 22



Audit Language:	English & Malay				
Audit Scope:	1.The audit covered One (1) site performing the following scope:				
	Operations, comprising of plantation management systems, production of Fresh				
	Fruit bunches (FFB), Production of Crude Palm Oil (CPO) and Palm Kernel (PK),				
	documentation and field assessment.				
	2.The audit covered all the MS2530-4:2013 Part 4 requirements with no permissible				
	exclusion of clause in compliance to the MSPO Certification Standard				

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main	Visit n°:	2
					Assessment		
CONFID	ENTIAL	Document:	GP 7003A	Issue n°:	10	Page n°:	4 of 22



Audit Plan

Date	Time	Auditor	Organizational and Functional Units/ Processes and activities	Key Contact
29 th Jan 2019	11.20 pm	DM/AK	Arrived to Miri Airport	Mill Personnel
30 th Jan 2019	7.00 am	DM/AK	Depart to Mill Opening Meeting Audit Process (Site Visit) Principal 1: Management commitment and responsibility Principle 2: Transparency Principle 3: Compliance to legal requirements Principal 4: Social responsibility, health, safety and employment condition Principal 5: Environment, natural resources, biodiversity and ecosystem services Principal 6: Best Practice	Mill Personnel
	12.30pm 1.00 pm		Lunch Continue Audit Process	
	1.00 pm		(Document review, Policies, local law compliances, deduction and pay slip, Safety and health procedures, environment procedure, minimum wages monitoring, social benefits)	
	4.00 pm		Preparation for closing	
5.00 pm			Closing Meeting	
	6.00 pm		Depart to Miri Airport	

Notes to Client:

- Times are approximate and will be confirmed at the opening meeting prior to commencement of the audit.
- SGS auditors reserve the right to change or add to the elements listed before or during the audit depending on the results of on-site investigation.
- A private place for preparation, review and conferencing is requested for the auditor's use.
- Please provide a light working lunch on-site each audit day.
- Your contract with SGS is an integral part of this audit plan and details confidentiality arrangements, audit scope, information on follow up activities and any special reporting requirements.

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main Assessment	Visit n°:	2
CONFIDE	ENTIAL	Document:	GP 7003A	Issue n°:	10	Page n°:	5 of 22



Location and Maps

The GPS locations of the mill is shown in Table 1.

Table 1: Alambumi Palm Oil Mill GPS Location

Mill:	Location Address:	GPS Coordinate(s):	Mill Capacity:
Alambumi Palm Oil Mill	Lot 79, Sawai Land District, KM 112, Jalan Miri-Bintulu, 98000 Miri, Sarawak	3°35'9"N 113°40'11"E	80mt/hr

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main	Visit n°:	2
					Assessment		
CONFIDENTIAL		Document:	GP 7003A	Issue n°:	10	Page n°:	6 of 22



Alambumi Palm Oil Mill Locality Map



,	Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main Assessment	Visit n°:	2
CONFIDENTIAL		ENTIAL	Document:	GP 7003A	Issue n°:	10	Page n°:	7 of 22



Description of Production Summary

The production are sourced from the estate which are directly managed by parent company related with Alambumi Palm Oil Mill Sdn. Bhd. The crop yield from the estate as mention in **Table 2** below.

Table 2: Production Summary 2018

MONTH	FFB PROCESSED (MT)	CPO PRODUCED (MT)	PK PRODUCED (MT)	OER (%)	KER (%)
JANUARY	42,514.32	8,067.15	1,968.07	18.98	4.63
FEBRUARY	38,572.33	7,328.33	1,801.86	19.00	4.67
MARCH	46,657.83	9,022.30	2,121.96	19.34	4.55
APRIL	49,534.88	9,720.54	2,239.12	19.62	4.52
MAY	48,736.47	9,566.04	2,099.71	19.63	4.31
JUNE	42,947.79	8,461.12	1,730.16	19.70	4.03
JULY	48,184.27	9,125.11	1,898.57	18.94	3.94
AUGUST	50,584.21	9,913.03	2,152.19	19.60	4.25
SEPTEMBER	53,382.31	10,363.17	2,304.82	19.41	4.32
OCTOBER	54,780.22	10,747.79	2,646.01	19.62	4.83
NOVEMBER	48,747.79	9,498.57	2,240.65	19.49	4.60
DECEMBER	41,862.07	7,973.85	1,873.29	19.05	4.47
YEAR TO DATE 2018	566,068.49	109,787.00	25,076.41	19.39	4.43

Table 3: Budget For Year 2019

FFB PROCESS	CPO PRODUCE	PK PRODUCE	OER	KER
(MT)	(MT)	(MT)	(%)	(%)
471,546.00	91,951.47	21,219.57	19.50	4.50

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main Assessment	Visit n°:	2
CONFIDENTIAL		Document:	GP 7003A	Issue n°:	10	Page n°:	8 of 22



Stakeholder Consultation and List of Stakeholders Contacted

A public announcement was made 30 days prior to the audit,

https://www.sgs.com/en/certified-clients-and-products/fcm/malaysia/-/media/C5C1475FDDB44F4C8C81738BC8D5AFC2.ashx

Stakeholder consultation took place in the form of meetings and interviews. Due to this is the main assessment, meetings with stakeholders were held in the estate office. Detail can be referred to **Appendix 1:**

Comment on MS2530-4 Compliance Status:

Comment on Prir	าсเช	ıe	1
-----------------	------	----	---

Policy on Implementation of MSPO -

The MSPO Policy was sighted available as per MSPO requirement dated 2nd October 2018. It was sign by Dato' Sri Lau Hieng Su (Executive Director). The policy emphasize commitment with MSPO, Alambumi Palm Oil Mill Sdn. Bhd. are committed to follow sustainable practices through continuous improvement in all our our operation.

Based interview with the staffs

1) Name: Rodney ak Paran

Position: Lead Machine at the maintenance area.

Year working: >1 year

2) Name: Affandi Bin Batok

Position: Maintenance area.

Year working: 4 years

Both of them are aware of the MSPO requirements in the mill area.

Internal audit

Internal audit was last conducted on the 30th October 2018

From mill internal audit, 19 findings was raised. Corrective action has already been taken, however report was produce to show corrective action taken. It will be verified in the stage 2 audit.

Management Review -

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main Assessment	Visit n°:	2
CONFIDENTIAL		Document:	GP 7003A	Issue n°:	10	Page n°:	9 of 22



The management review conducted on 2nd November 2018. In the agenda meeting it was discuss on:

- i. Minutes from previous management review.
- ii. The policies, objective and target.
- iii. Result of internal audit.
- iv. Suggestion & complaint.
- v. Other matters.

Continual Improvement

The Management review report on continual improvement includes the following:

- 1) To construct new store to store the empty drum and gallon.
- 2) To buy Biotube for desludging and reduce the amount of silted sludge.

Comment on Principle 2

Transparency of documents relevant to MSPO requirements -

The mill management will communicate all information requested by relevant stakeholders thru mill. This will be based on types of inquiry. All information relating to external stakeholder will be responded by HQ top management.

The mill stakeholders communication flowchart was shown during audit Document No : ABPOM-MSPO-P2-COM-001

The management will communicate with interested stakeholders on information requested and reply accordingly.

Latest Stakeholders meeting was recorded on 30th October 2018 at Mill meeting room. It was attended by 67 attendees of several stakeholders.

However, based on site inspection during delivery of FFB at the mill, it was observed the Personnel Protective Equipment (PPE) was not implement adequately by smallholders during loading the FFB

Management documents for the mill are made publicly available upon request.

Transparent method of communication and consultation

The company has established a Procedure on the mill stakeholders communication in Document No: ABPOM-MSPO-P2-COM-001 dated 28th September 2018 for consultation and communication with the relevant stakeholders.

The document also includes a flow chart of 'Request Info from Stakeholders and responses"

Grievances Box was made available at site office. Grievances procedure document: ABPOM-MSPO-P4-CG-001 was made available at site

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main Assessment	Visit n°:	2
CONFIDENTIAL		Document:	GP 7003A	Issue n°:	10	Page n°:	10 of 22



List of external and internal stakeholders was made available on site which includes Government agencies, companies, supplier etc. Traceability In the Mill Manual, the document for the implementation and maintenance of the requirements for traceability is documented. Traceability and Mass Balance It include the following sections: 1) Purpose 2) Scope 3) Responsibilities 4) Definition 5) Procedure They have a flowchart to show how to trace back a delivery form the FFB source. Comment on Principle 3 Regulatory requirements -Compliance to Applicable local state and national law It was observed the machineries validity was up-to-date; Some of the validity list as below under Factories and Machineries Act Perakuan Kelayakan Pengandung Tekanan Tak Berapi : FMA 1967 Regulations 10 (2) No Pendaftaran: a) SW PMT 4985, Valid till 2nd August 2019 MPOB License: No Lesen: 509026404000 Validity: 1/8/2018-31/07/2019 1.License: menjual & mengalih FFB, PK, CPO, SPO# 2. Membeli & mengaih FFB, PK, CPO# 3.Menyimpan PK, CPO, SPO# 4.Mengilang FFB# DOE Jadual Pematuhan: 03006 Tempoh Lesen: 1 July 2018-30 Jun 2019.

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main Assessment	Visit n°:	2
CONFIDENTIAL		Document:	GP 7003A	Issue n°:	10	Page n°:	11 of 22

Based on interview with legal officer Mr. Victor Lau Mechanism to track



changes or new amendments in law using website.

Legal land use rights -

Alambumi Palm Oil Mill Sdn. Bhd. is located within Lot number 283 in

Block/ Number 22 containing 41.1 hectares.

Lease of State Land

Locality: Kilometre 112, Jalan Miri-Bintulu, Suai, Niah.

Classification : Mixed Zone Category : Country Land

Land register
Date: 26/05/2014

Map Sheet No: G16 -4-3(1.2) BP 4/729 Commencement and Expiry Date :

27/04/1998-26/04/2058

Mill Complex Area Total Area: 41.1 ha Total Ponds: 17 Treatment Plant: 12 Water Reservoir: 5 Housing Units: 157 units

Customary rights -

The legal acquisition was proven via availability of land title from Land and Survey Sarawak.

Commencement and Expiry Date:

27/04/1998-26/04/2058

Registered Office: Miri

Comment on Principle 4

Social Impact Assessment -

Alambumi Palm Oil Mill Sdn. Bhd. presented the stakeholders meeting minute, feedback and list of stakeholders attended.

The stakeholders meeting has been conducted on 30th October 2018 with only attend by .Noted that total stakeholders are 67. The meeting conducted at Mill office.

The meeting discussed on

- -MSPO certification introduction and briefing
- -Briefing on grievance procedure

Complaints and grievances -

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main Assessment	Visit n°:	2
CONFIDENTIAL		Document:	GP 7003A	Issue n°:	10	Page n°:	12 of 22



It was observed the Standards Operation Procedure for complains and grievances procedure was available, which can refer in file Standard Operation Procedure (SOP).

Document No: ABPOM-MSPO-P4-CG-001

Commitment to contribute to local sustainable developments -

Days complaint to solved : 12 days Person in charge: Mr Ch'ng Wee Ming.

Three complaints was recorded and sighted during audit.

- 1.Franky ak Gaji
 - Pemandu lori selalu tidak menurunkan Bucket.
 - Harga barangan dikantin terlalu mahal.
- 2. Supply water to Mill and Estate quarters.
- Pemeriksaan mata bagi warga tua & murid sekolah (24th Nov 2018) for Kampung Muslim Penan Jambatan Suai KK Mohammad Yusuf B. Abdullah.
- 4.Sumbangan Hari Keluarga MPOB Cawangan Miri/ Cawangan

Limbang & Cawangan Niah 2018.

 Sumbangan/ Derma bagi Program "HIP: Fund Raising Day" SK Batu Tellingai.

It can be verified in File Alambumi Palm Oil Mill Sdn. Bhd. "Sumbangan Masyarakat"

Employees health and safety -

Safety and health policy was incorporated within MSPO General policy.

The Safety and health statement was signed by the Ms Adeline Lau Kor See (Director) dated 13th July 2018

Among the safety objective:

- 1. Provide safe working environment to the workers / staff
- 2.To train all employee to be aware of their own responsibility
- 3.To provide appropriate medical and first aid facilities to safeguard the health and ware fare of all our employees

Major 1 Principle 4.4.4.2

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main Assessment	Visit n°:	2
CONFIDENTIAL		Document:	GP 7003A	Issue n°:	10	Page n°:	13 of 22



The occupational safety and health plan was established. However, the implementation was found inadequate.

Employment conditions -

In the Wawasan Sedar Palm Oil Mill policy on 'Social and Community Policy ' signed by Mr Andrew Esi and Mr Cheng Hua Biew

The policy mentioned 'Respect and Protection of Human Right of employees and eliminate discrimination in employment and promote equal right,"

Interview with MS Irene (Senior Clerk) shows that she is aware with the policy.

Major 2

Principle 4.4.5.11

On-site living quarters are provided to the mill workers and these quarters was identified to be habitable. However, collection drain at housing site was found not maintain.

Training and competency -

The occupational safety and health plan known as 'Annual Training Programme Jan – Dec 2018 ' cover the following:

There are 27 topics listed in the training which include:

- 1) Grading skills
- 2) Accident Reporting
- 3) Register of chemical Hazardous & chemical handling
- 4) HIRARC
- 5) ERP
- 6) First Aid Training
- 7) Confined space

Comment on Principle 5

Environmental management plan -

The management has provided Sustainability Policy which included environment component.

The policy signed by General Administrative Manager (Mr. Cheng Hua Biew) and Mill Manager (Mr Andrew Ak Esi) dated :1st June 2018

The policy commits to achieve environmental sustainability by

- i. Safety and Health
- ii. Environment
- iii. Good Social Practices
- iv. Harassment & Violence Prevention

The management has provided continual improvement plan for Wawasan Sedar Palm Oil Mill for 2018.

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main	Visit n°:	2
					Assessment		
CONFIDENTIAL		Document:	GP 7003A	Issue n°:	10	Page n°:	14 of 22



Item incorporate in the plan are list as below:

- i. First Aid Training
- ii. Fire Fighting Equipment Training
- iii. Safety data sheet training
- iv. Driver Training and awareness
- v. HIRARC.

It was observed the training record was made available:

i. Training/ Course: Chemical Safety Management, dated 20th September 2018, time:10.00 am, venue WSPOM Conference room, which train by Mr. Empajang/ Sabih, attended by 21 attendees.

The continual improvement plan will be monitored by the mill management through their quarterly meeting

Example: "Mesyuarat Jawatankuasa Pengawasan Prestasi Alam Sekitar (ERCMC)(Bil: 1/2018)". Dated of meeting 19th October 2018, meeting room of WSPOM which attend by "Ahli Jawatankuasa ERCMC Wawasan Sedar Palm Oil Mill"

The agenda discuss as below:

- i. Environmental Improvement Projects
- ii. Effectiveness of environmental policy and follow up actions.
- iii. New environmental regulatory amendments and implications
- iv. Major initiatives on major non-conformance (NC) issue.
- v. Environmental impact on procurement and purchasing policies.

Major 3

Principle 4.5.3.2

Waste management was found lacking.

Efficiency of energy use and use of renewal energy -

On the Energy Optimization Plan, the management has provides diesel consumption record that shows diesel usage record as below:

Usage of diesel record (Litres)

	2016	2017	2018*
Actual	513,103	645,269	489,228
Budget	Nil	Nil	Nil

^{*}as September 2018

Increasing usage of diesel due to low crop season where power plant not operation and it increasing usage of genset to generate power supply.

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main Assessment	Visit n°:	2
CONFID	ENTIAL	Document:	GP 7003A	Issue n°:	10	Page n°:	15 of 22



Waste management and disposal -

a)The management show record for its waste products in their 2018 inventories

It was observed the Standard Operating Procedure for handling of used chemicals was made available at the mill premise. The document Name: Chemical Handling with Document ref no.: WSPOM-03-SH06/REV0 dated 2nd May 2018.

Location of dumping site was made available

During site inspection it was observed there was no scheduled waste inside the dumping site.

It was observed the Waste management plan was made available with document name: Waste Management, Document Ref.: WSPOM-03-EN03/ REV0.

Types of waste was list as below:

- i. Domestic waste
- ii. Scheduled waste
- iii. Product waste: Empty Fruit Bunches
- iv. Product waste: Mesocarp Fiber
- v. Product waste: Palm Kernel Shell
- vi. Product waste: Palm oil mill effluent (POME)

Product waste: Decanter cake

Reduction of pollution and emission including greenhouse gas – The management has provided :

1. Environment Monitoring report for Boiler 1 and 2 latest: cover for July till December 2018. The conclusion for both area states as below:

Summary

<u>Boiler No.1</u>: The dust emission as measured in Boiler No.1 at Alambumi Palm Oil Mill Sdn. Bhd. on 22nd of October 2018, from 1430 hours to 1536 hours for Boiler No. 1 was 0.390 g/Nm³ and this result was below the allowable standard emission limit of 0.400 g/Nm³, corrected at 12% CO₂.

<u>Boiler No.2</u>: The dust emission as measured in Boiler No.2 at Alambumi Palm Oil Mill Sdn. Bhd. on 9^{th} July 2018, from 1100 hours to 1250 hours for Boiler No. 2 was 0.391 g/Nm³ and this result was below the allowable standard emission limit of 0.400 g/Nm³, corrected at 12% CO₂.

Natural water resources -

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main Assessment	Visit n°:	2
CONFID	ENTIAL	Document:	GP 7003A	Issue n°:	10	Page n°:	16 of 22



The management has provided 1.water testing analysis for drinking water (latest 26th March 2018)

File:Teknologi Enviro Kimia

Ref. Lab. no.:LS/PO/F9870/18

From the analysis, it was noted that the domestic water quality was within permit limit for water consumption based on National Water Quality Standard (NWQS)

The monitoring of the implementation of water management plan is overall done by the Mill Manager.

Comment on Principle 6

Mill management -

The management has provided Safety Operation Procedure (SOP) on Mill Operations with regards to MSPO, all of the SOP which includes:

- i. Sterilizer
- ii. Tipper
- iii. Thresher
- iv. Digester
- v. Screw Press
- vi. Weighbridge
- vii. FFB Ramp

- viii. FFB Ramp
 viii. FFB Conveyor
 ix. Transfer Carriage
 x. Shovel, Excavator and Palm Tractor
 xi. Rails and Marshalling Yard
- xii. Fruit Cage
- xiii. Grading Procedures
- xiv. Grading Frequency
- xv. Bunch Classifications
- xvi. Crossover Bridge

Other SOP can be verified in the SOP file.

The SOP will be amended by the Head of Mill if any changes in SOP.

Economic and Financial Vialibility Plan -

The management has provided 2 years production projection for year 2018-2019 (in MT)

Year FFB <u>CPO</u> PΚ 2018 399, 915 80,982.79 17,996.18 2019 471,546 91,951.47 21, 219.57

The document can be verified in yearly budget report for 2018 and 2019.

Transparent and fair pricing dealing -

The mill management receives FFB from internal and external suppliers related plantations which under the same group.

Job ı	n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main	Visit nº:	2
						Assessment		
CON	IFIDE	ENTIAL	Document:	GP 7003A	Issue n°:	10	Page n°:	17 of 22



Internal FFB

- Alto Sdn. Bhd.
- Alamwasa Sdn. Bhd.
- Bumi Hijau Berkembang Sdn Berhad
- Regalot Pelita Plantation Sdn. Bhd.

External FFB

- TH Pelita Niah
- TH Pelita Bakong
- Simalau
- Melemas
- Green Field
- Origrow Venture
- Golden Palm Harvest (Ramp)

Sales and purchase agreements.

Document No: WSPOM/HP/18

Pricing mechanism:

According to Mr. George Anak Akam, the pricing mechanism for Alambumi POM for FFB purchase are spelt out in the Internal Contract Agreement as it receives crop from internal sources. All will be based on MPOB website.

Similarly for the sale of Crude Palm Oil and Palm Kernel Oil are spelt out in the Internal Contract Agreement.

Refinery: Bintulu Edible Oil Refinery.

Contractor

The management has provided list of contractors:

- 1. Kunciraya Sdn. Bhd. for transporting of FFB
- 2. Metro Sepadan Sdn. Bhd. as sub-contractor for Kunciraya.
- 3. Nabbir Laboratory (Sarawak) Sdn Bhd for water sampling and laboratory
- 4. Kien San (Metal) Sdn. Bhd. for Scrap metal transportation and storage. (DOE licence N. 001739 and No. 001740).

The sign of agreement mentioned on MSPO compliances was sighted in the addendum of the contract agreement

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main	Visit n°:	2
					Assessment		
CONFID	ENTIAL	Document:	GP 7003A	Issue n°:	10	Page n°:	18 of 22



7. Non nonconformity

MS2530-4:2013 Part 4

MS2530-4:2013 Part 4 General principles for Palm Oil Mills

CAR#	Indicator			C	AR Detail				
1 MS2530- 4:2013	4.4.4.2	Date Recorded>	30 th January 2019	Due Date>	30 th March 2019	Date Closed>	20 th March 2019		
Part 4		Non-Confor	mance:						
		The occupational safety and health plan was established. However, the implementation was found inadequate.					er, the		
		Objective Ev	/idence:						
During site tour and document assessment, it was sighted									
a) Unsafe condition at workplaces was sighted at the scheduled was area and mill operation area.					waste store				
	b) The risk assessment for working during night shift was not available. In temergency action plan, there is no action to be taken in an event of power / electric breakdown during night shift.								
		c) Fire exting	uisher was f	ound exp	ired at housing	g ABQ Block 20	Block 20B		
		d)Replacement item in the first aid box was not documented							
		e) Chemical I labeling proc	•	ne laborato	ory was found	not following ch	emical		
		Close-out ev	/idence:						
		conformity ra of pictures of assessment of of equipment	ised based on installation installation installation installation including fired by the miles.	on the 4.4 on of safe or women to re extingu	I.4.2 findings. ety signage, that work durir iisher, first aid	ive action to on the corrective are guard, upoing night time and box and chemic rective action was	action consists dating on risk d management ical equipment		

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main Assessment	Visit n°:	2
CONFID	ENTIAL	Document:	GP 7003A	Issue n°:	10	Page n°:	19 of 22



2 MS2530- 4:2013	4.4.5.11	Date Recorded>	30 th January 2019	Due Date>	30 th March 2019	Date Closed>	20 th March 2019
Part 4		Non-Confor	mance:				
			e habitable	•		kers and these of at housing site	•
		Objective Evidence:					
		During site visit to housing ABQ Block 20, it was sighted collection drain properly maintained					drain not
		Close-out evidence:					
		maintenance	issue. Pict	ures of drain	desalting and	on workers quart time table of fut accepted by au	ure drainage

3 MS2530- 4:2013	4.5.3.2	Date Recorded>	30 th January 2019	Due Date>	30 th March 2019	Date Closed>	20 th March 2019
Part 4		Non-Confor	mance:				
		Waste mana	igement wa	s found lack	ing		
		Objective Ev	/idence:				
		1. Scheduled waste was found at the domestic dumping site during site visit. The				g site visit. The	
		empty m-oil o		•			
		2.Labeling of	scheduled	waste in lab	oratory was fo	und inadequate	
		Close-out ev	/idence:				
		procedure was scheduled was	hich incluaste. The s	des proper cheduled wa	labelling gui ste collector a	heduled waste idance and m ppoint was shou ut evidence wa	anagement of wn in close out

Nonconformities detailed here shall be addressed through the organization's corrective action process, in accordance with the relevant corrective action requirements of the audit standard, including actions to analyse the cause of the nonconformity and prevent recurrence, and complete records maintained.

Corrective actions to address identified major nonconformities shall be carried out immediately and SGS notified of the actions taken within 30 days. An SGS auditor will perform a follow up visit within 60 days to confirm the actions taken, evaluate their effectiveness, and determine whether certification can be granted or continued.
Corrective actions to address identified major nonconformities shall be carried out immediately and records with supporting evidence sent to the SGS auditor for close-out within 60 days.
Corrective Actions to address identified minor non conformities shall be documented on an action plan and sent by the client to the auditor within 60 days for review. If the actions are deemed to be satisfactory they will be followed up at the next scheduled visit

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main Assessment	Visit n°:	2
CONFIDE	ENTIAL	Document:	GP 7003A	Issue n°:	10	Page n°:	20 of 22



Corrective Actions to address identified minor non-conformities have been detailed on an action plan
and the intended action reviewed by the Auditor, deemed to be satisfactory and will be followed up at
the next scheduled visit.

Appropriate immediate action taken in response to each non-conformance as required

Note:- Initial, Re-certification and Extension audits – recommendation for certification cannot be made unless check box 4 is completed. For re-certification audits the time scales indicated may need to be reduced in order to ensure re-certification prior to expiry of current certification.

Note: At the next scheduled audit visit, the SGS audit team will follow up on all identified nonconformities to confirm the effectiveness of the corrective actions taken.

8. General Observations & Opportunities for Improvement

Positive Observations:

- The support from Alambumi Palm Oil Mill Sdn. Bhd. personnel, especially the ground staff contribute to the smoothness and successful of the audit process.
- The spirit of unity and enthusiasm of the personnel towards achieving MSPO certification is impressive.
- The unit has dedicated staffs who are assets to the company. Their cooperative, knowledgeable and hospitability are commendable
- Organised documentation & highly commitment towards certification.

Appendix 1: List of Stakeholders Contacted

Stakeholder	Type of Stakeholder	Issues raised	Comments/Action Taken
Monica Mone MPOCC	External (Government)	NIL	No issue
Andrea Chin WWF Malaysia	External (NGO)	NIL	No issue
Rodney ak Paran	Internal (Staff)	NIL	Based on interview, the stakeholder aware regarding the MSPO.

Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main	Visit n°:	2
					Assessment		
CONFID	ENTIAL	Document:	GP 7003A	Issue n°:	10	Page n°:	21 of 22



Affandi Bin Batok	Internal (Staff)	NIL	Awareness good
Dr Felix Moh Alto Group Estate Coordinator	FFB Supplier (ALTO Group of Plantations)	NIL	NIL



Job n°:	MY05223	Report date:	30.01.2019	Visit Type:	Main	Visit n°:	2
					Assessment		
CONFID	ENTIAL	Document:	GP 7003A	Issue n°:	10	Page n°:	22 of 22